## **User Manual**

# **EM1** series

2-Phase Digital Stepper Drive



## Hardware Version 1.0 Manual Revision 1.0

©2024 China Leadshine Technology Co., Ltd.

Address: 15-20/F, Block B, Nanshan I Valley, No.3185, Shahe West Road, Nanshan District,

Shenzhen, Guangdong, 518055, China

*Tel*: (86)755-26409254 *Fax*: (86)755-26402718

Web: www.leadshine.com Sales: sales@leadshine.com

Support: tech@leadshine.com



#### **Notice**

Read this manual carefully before any assembling and using. Incorrect handling of products in this manual can result in injury and damage to persons and machinery. Strictly adhere to the technical information regarding installation requirements.

This manual is not for use or disclosure outside of Leadshine except under permission. All rights are reserved. No part of this manual shall be reproduced, stored in retrieval form, or transmitted by any means, electronic, mechanical, photocopying, recording, or otherwise without approval from Leadshine. While every precaution has been taken in the preparation of the book, Leadshine assumes no responsibility for errors or omissions. Neither is any liability assumed for damages resulting from the use of the information contained herein.

This document is proprietary information of Leadshine that is furnished for customer use ONLY. Information in this document is subject to change without notice and does not represent a commitment on the part of Leadshine. Therefore, information contained in this manual may be updated from time-to-time due to product improvements, etc., and may not conform in every respect to former issues.

#### **Record of Revisions**

<b>Manual Revision</b>	Date	<b>Description of Release</b>
1.0	Apr, 2024	Initial Release
1.1	Apr, 2025	Filter setting updating





## **Table of Contents**

1. Features	
2. Specifications	1
2.1 Electrical Specifications	1
2.2 Environment	2
2.3 Mechanical Specifications	2
2.4 Elimination of Heat	3
3. Connection Pin Assignments and LED Indication	
3.1 P1 - Control Connector	3
3.2 P2 - Fault Output Connector	4
3.3 P3 - Motor and Power Supply Connector	4
3.4 P4 - RS232 Tuning Port	
3.5 LED Light Indication	
4. Control Signal and Output Signal	5
4.1 Control Signal Connection	5
4.2 Fault Output Connection	5
5. Motor Connection	6
6. Power Supply Selection	7
6.1Power Supply Sharing	7
6.2 Selecting Supply Voltage	7
7. DIP Switch Configurations	7
7.1 Microstep Resolution Configurations	9
7.2 Output Current Configurations	9
7.2.1 Dynamic Current Configurations	错误! 未定义书签。
7.2.2 Idle Current Configuration	错误! 未定义书签。
7.3 Automatic Motor Matching & Self Configuration	10
8. Wiring Notes	
9. Typical Connection	10
10. Sequence Chart of Control Signals	11
11. Protection Functions	11
12. Troubleshooting	13
13. Warranty	14



#### 1. Features

- Step & direction (PUL/DIR) control
- Input voltage 20-50VDC (recommended 24-48VDC)
- 500 KHz max pulse input frequency
- 15 microstep resolutions of 400-25000 via DIP switches
- 7 output current settings of 1.0-4.2A via DIP Switches
- Idle current reduction to 50% or 90% selection via SW4
- Auto-tuning to match wide-range NEMA 11, 17, 23 and 24 stepper motors
- Anti-Resonance for optimal torque, extra smooth motion, low motor heating and noise
- Soft-start with no "jump" when powered on
- Optically isolated inputs with 5V or 24V
- Fault output
- Over-voltage and over-current protections

## 2. Specifications

#### 2.1 Electrical Specifications

_							
	Drive Model	A Commence of the Commence of	A THE PARTY OF THE	III III III III III III III III III II	The second	The section of the se	It is the state of
		EM1-422	EM1-432	EM1-542	EM1-556	EM1-870	EM1-882AC
	Dimension (L*W*H)	86*55.	5*20.5	118*75.5*25.5	118*7	5.5*34	151*97*52
	Matching Motors (Frame Size)	20/28/35/42	35/42	57	57/60	60/86	86
	Input Voltage	20~36Vdc	20~36Vdc	24~50Vdc	24~50Vdc	24~80Vdc	20~70Vac 30~100Vdc
	Max. Continuous Current Output	2.2A	3.2A	4.2A	5.6A	7.0A	8.2A
	Pulse Voltage Input	5~24Vdc					
	Max. Pulse Frequency	200kHz、500kHz Configurable					
	Max. Current Output (Signal)	100mA (30Vdc Max. Voltage)					




#### 2.2 Environment


Cooling	Natural Cooling or Forced cooling		
	Environment	Avoid dust, oil fog and corrosive gases	
On anotin a Environment	Humidity	40%RH-90%RH	
Operating Environment	Operating Temperature	0°C - 40°C (32°F - 109°F)	
	Vibration	10-50Hz / 0.15mm	
Storage Temperature	-20°C — 65°C (-4°F - 149°F)		
Weight	Approx. 230g (0.51 lbs)		

## 2.3 Mechanical Specifications

(unit: mm [1inch=25.4mm])



• Figure 1 EM1-542 Installation Dimension Drawing



• EM1-556,EM1-870 Installation Dimension Drawing



#### 2.4 Elimination of Heat

- EM1 reliable working temperature should be < 40°C (109°F)
- It is recommended to use automatic idle-current mode to reduce motor heating. That means set the SW4 pin of DIP switch at "OFF" position.
- It is recommended to mount the drive vertically to maximize heat sink area. Use forced cooling method to cool if necessary.

## 3. Connection Pin Assignments and LED Indication




Figure 2 Connectors, DIP switches, and LED locations

The EM1 has three connector blocks P1&P2&P3 (see above picture). P1 is for control signals connections, and P2 is for output signals connections, P3 is for power and motor connections. The following tables are brief descriptions of the three connectors. P4 is for modifying parameters More detailed descriptions are as below.

#### 3.1 P1 - Control Connector

PIN	Details
PUL+	Pulse and Direction Connection:  (1) Optically isolated, high level 4.5-5V or 24V, low voltage 0-0.5V
PUL-	(2) Maximum 200 KHz input frequency
DIR+	<ul> <li>(3) The width of PUL signal is at least 2.5μs, duty cycle is recommended 50%</li> <li>(4) DIR signal requires advance PUL signal minimum 5 μs in single pulse mode</li> </ul>
DIR-	(5) The factory setting of control signal voltage is 24V, must need to set S2 (figure 2) if it is 5V
ENA+	Enable Connection: (default no connection) (1) Optically isolated, differential.



ENA-

- (2) Disable the drive by 4.5- 24V input connection; enable the drive by 0-0.5V connection
- (3) ENA signal requires advance DIR signal minimum 5µs in single pulse mode
- (4) Enable time to be at least 200ms

#### **Notes:**

- (1) Shield cables are required for P1;
- (2) Don't tie P1/P2 cables and P3 cables together.

#### 3.2 P2 - Fault Output Connector

Pin	Details
4736	(1) Maximum 30V/100mA output
ALM+	(2) Sinking or sourcing
	(3) The resistance between ALM+ and ALM- is low impedance as default, and will change to
<b>ALM-</b> high when the drive goes into error protection.	
	(4) Fault connection refer to <u>chapter 4.2</u>

#### 3.3 P3 - Motor and Power Supply Connector

Pin Function	Details
GND	Power supply ground connection.
+Vdc	Power supply positive connection. Suggest 24-48VDC power supply voltage
A+, A-	Motor Phase A connections. Connect motor A+ wire to A+ Pin; motor A- wire to A-
B+, B-	Motor Phase B connections. Connect motor B+ wire to B+ Pin; motor B- wire to B-



Warning Warning: Don't plug or unplug the P1 & P2&P3 terminal block to avoid drive damage or injury when EM1 is powered on.

#### 3.4 P4 - RS232 Tuning Port

The P4 connector in Figure 3 is a RS232 communication port for PC connection. Refer to the following pin definitions. It is just used to modify parameter, not for equipment control because neither precision nor stability is sufficient. If you need a field bus drive, use a Leadshine RS485 or EtherCAT type drives

The interface definition is as follows:




Figure 3 RS232 tuning port

#### 3.5 LED Light Indication

There are two LED lights for EM1. The GREEN one is the power indicator which will be always on generally. The



RED one is a protection indicator which will flash 1-2 times in a 3-second period, when protection enabled for a EM1. Different number of flashes indicates different protection type (read section 11 for detail).

## 4. Control Signal and Output Signal

#### 4.1 Control Signal Connection

The EM1 can accept differential or single-ended control signals (pulse, direction, and enable) in open-collector or PNP connection through the P1 connector (figure 2). It is recommend to add an EMI line filter between the power supply and the drive to increase noise immunity for the drive in interference environments.

Single-ended connection method:




Figure 4: Connections to open-collector signal (common-anode)





Figure 5: Connections to PNP signal (common-cathode)

#### **Notes:**


- (1) ENA signal is no-connected as default;
- (2) Control signal amplitude is 24 V as default. When connect to a 24V pulse signal, there is no need to string resistor, and the factory default is effective on the falling edge.

#### 4.2 Fault Output Connection

When over voltage or over current protection happens, EM1 red status LED light will blink and the impedance state between ALM+ and ALM- will change (from low to high or high to low depending on configuration) and can thus be detected. Fault output connection is optional, and it can be connected either in sinking or sourcing.



Connecting a sourcing output to a PLC's input



Driving a relay




Figure 6 Fault Connection


#### 4.3 Wiring method of motor with brake

Relay wiring refers to the pictures below. Because the coil of brake and relay are sensitive load, it is recommended to add a diode, the diode model can choose ordinary rectifier diode (such as: IN4007). In addition, diode polarity must not be connected in reverse.

We also suggest customers to use solid state relay, in this condiction there is no need to add a diode. Solid state relay advantages: fast response speed, no need to add diode, through and break without sound; recommended to use "Kaiser" KS 1-10DD model solid state relay.



Ordinary relay connect the motor with brake



Solid state relay connect the motor with brake



#### 5. Motor Connection

The EM1 can drive 2-phase and 4-pahse bipolar hybrid stepper motors.

The 4 lead motors are the least flexible and easy to connect. The output current from drive that is multiply the specified phase current by 1.4 to determine the peak output current.




Figure 7 4-lead Motor Connections

## 6. Power Supply Selection

The EM1 can power medium and large size stepping motors (frame size from NEMA 11 to 24). To get good driving performances, it is important to select supply voltage and output current properly. Generally speaking, supply voltage determines the high speed performance of the motor, while output current determines the output torque of the driven motor (particularly at lower speed). Higher supply voltage will allow higher motor speed to be achieved, at the price of more noise and heating. If the motion speed requirement is low, it's better to use lower supply voltage to decrease noise, heating and improve reliability.

#### 6.1Power Supply Sharing

Multiple EM1 drives can share one power supply to reduce cost, if that power supply has enough power capacity. To avoid cross interference, connect each stepper drive directly to the shared power supply separately. To avoid cross interference, DO NOT daisy-chain connect the power supply input pins of the Drivers. Instead connect them to power supply separately.

#### 6.2 Selecting Supply Voltage

The EM1 is designed to operate within 18 - 50VDC voltage input. When selecting a power supply, besides voltage from the power supply power line voltage fluctuation and back EMF voltage generated during motor deceleration needs also to be taken into account. Please make sure leaving enough room for power line voltage fluctuation and back-EMF voltage charge back.

Higher supply voltage can increase motor torque at higher speeds, thus helpful for avoiding losing steps. However, higher voltage may cause bigger motor vibration at lower speed, and it may also cause over-voltage protection or even drive damage. Therefore, it is suggested to choose only sufficiently high supply voltage for intended applications.


## 7. DIP Switch Configurations

The EM1 has two sets of DIP switches. The first set is used to configure settings of micro step resolution, output current, motor standstill current, pulse type and smoothing time as shown below. The second set can be used to set



filter time, double pulse mode, limit pulse frequency 500 kHz (default 200 kHz), etc

## 7.1 Dip switches 1



1) driver output current setting (DIP Switches SW1~SW3)

#### ■ EM1-542

EIVII 5-12				
SW1	SW2	SW3	Drive current Peak (A)	Drive current RMS (A)
OFF	OFF	OFF 1.0 (default) 0.7		0.7
ON	OFF	OFF	1.5	1.1
OFF	ON	OFF	1.9	1.4
ON	ON	OFF	3.4	1.7
OFF	OFF	ON	2.8	2.0
ON	OFF	ON	3.3	2.4
OFF	ON	ON	3.8	2.7
ON	ON	ON	4.2	3.0

#### ■ EM1-556

SW1	SW2	SW3	Drive current Peak (A)	Drive current RMS (A)
OFF	OFF	OFF	1.8 (default)	1.3
ON	OFF	OFF	2.1	1.5
OFF	ON	OFF	2.7	1.9
ON	ON	OFF	3.2	2.3
OFF	OFF	ON	3.8	2.7
ON	OFF	ON	4.3	3.1
OFF	ON	ON	4.9	3.5
ON	ON	ON	5.6	4.0

#### ■ EM1-870

SW1	SW2	SW3	Drive current Peak (A)	Drive current RMS (A)
OFF	OFF	OFF	1.4 (default)	1.0
ON	OFF	OFF	2.6	1.8
OFF	ON	OFF	3.4	2.4
ON	ON	OFF	4.0	2.8
OFF	OFF	ON	4.8	3.4
ON	OFF	ON	5.4	3.8
OFF	ON	ON	6.1	4.3
ON	ON	ON	7.0	5.0



#### Illustrate:

#### When SW1~3 are OFF, the driving current can be set by the debugging software.

#### 2) Idle Current Configuration

SW4 is used to set motor idle current percentage. At OFF position it means the standstill current is set to be 50% of the selected output current. At ON position it means standstill current is set to be 90%.

The current automatically reduced to 50% of the selected dynamic current 0.4 second after the last pulse.

#### 3) Microstep Resolution Configurations

Microstep resolution is set by SW5, 6, 7, 8 of the DIP switches as shown in the following table. Note: "default" means the parameters can be set by Leadshine software.

Microstep	Steps/rev.(for 1.8°motor)	SW5	SW6	SW7	SW8
1	200 (default)	ON	ON	ON	ON
2	400	OFF	ON	ON	ON
4	800	ON	OFF	ON	ON
8	1600	OFF	OFF	ON	ON
16	3200	ON	ON	OFF	ON
32	6400	OFF	ON	OFF	ON
64	12800	ON	OFF	OFF	ON
128	25600	OFF	OFF	OFF	ON
5	1000	ON	ON	ON	OFF
10	2000	OFF	ON	ON	OFF
20	4000	ON	OFF	ON	OFF
25	5000	OFF	OFF	ON	OFF
40	8000	ON	ON	OFF	OFF
50	10000	OFF	ON	OFF	OFF
100	20000	ON	OFF	OFF	OFF
125	25000	OFF	OFF	OFF	OFF

#### 7.2 DIP Switch 2

### 1) Filter setting (SW10)

SW10	illustrate
ON	Filtering time 0ms
OFF	Filtering time 10ms (default )



2) other switch function settings (SW11~16)

Dip Switch	Function	Description
SW11	auto-tuning setting	SW11=ON: The motor is not self-tuning when powered on, and the default parameters are used; SW11=OFF: Self-tuning of the motor at power-on (factory default).
SW12	Alarm output configuration setting	SW12=ON: Low level effective (not conduction)  Under normal working conditions, the alarm output is high resistance (not conductive state), when the driver alarm, the alarm output is low resistance (conduction state);  SW12 =OFF: high level effective (conduction) (factory default)  Under normal working conditions, the alarm output is low resistance (conduction). When the driver has an alarm, the alarm output is high resistance (non-conduction).
SW13	Effective along settings	SW 13 = ON: valid (factory default); SW 13 = OFF: Pulse rising edge is active.
SW14	Single and double pulse mode setting	SW 14 = ON: set to dual-pulse mode; SW 14 = OFF: Set to Pulse + directional mode (factory default).
SW15	Limit pulse frequency selection	SW15=ON: 500kHz; SW15=OFF: 200kHz (factory default) 。
SW16	Gain mode selection	SW 16 = ON: high response mode; SW 16 = OFF: low-vibration mode (factory default).

#### 7.3 Automatic Motor Matching & Self Configuration

When powered on a EM1 will automatically configure itself with the best settings to match the driven stepper motor for optimal performance. No action is needed.

## 8. Wiring Notes

- In order to improve anti-interference performance of the drive, it is recommended to use twisted pair shield cable.
- To prevent noise incurred in PUL/DIR signal, pulse/direction signal wires and motor wires should not be tied up together. It is better to separate them by at least 10 cm, otherwise the disturbing signals generated by motor will easily disturb pulse direction signals, causing motor position error, system instability and other failures.
- If only one power supply serves multiple EM1 drives, separately connecting the drives to the power supply is recommended instead of daisy-chaining.
- It is prohibited to pull and plug connector P2 while the drive is powered ON, because there is high current flowing through motor coils (even when motor is at standstill). Pulling or plugging connector P2 with power on will cause extremely high back-EMF voltage surge, which may damage the drive.

## 9. Typical Connection

A complete stepping system should include stepping motor, stepping drive, power supply and controller (pulse generator). A typical connection is shown as below.






Figure 8 Typical Connections

## 10. Sequence Chart of Control Signals

In order to avoid some fault operations and deviations, PUL, DIR and ENA should abide by some rules, shown as following diagram:




Figure 9 Sequence chart of control signals

#### Remark:

- a) t1: ENA must be ahead of DIR by at least 200ms. Usually, ENA+ and ENA- are NC (not connected). See "Connector P1 Configurations" for more information.
- b) t2: DIR must be ahead of PUL effective edge by 5µs to ensure correct direction;
- c) t3: Pulse width not less than 2.5 µs;
- d) t4: Low level width not less than 2.5 µs;
- e) Duty cycle of Pulse signal is recommend 50%.

#### 11. Protection Functions

To improve reliability, the drive incorporates some built-in protections features.



Priority	Time(s) of Blink	Sequence wave of red LED	Description
1st	1		Over-current protection activated when peak current exceeds the limit.
2nd	2		Over-voltage protection activated when drive working voltage is greater than 60VDC
3nd	3		Reserved.

When above protections are active, the motor shaft will be free or the red LED blinks. Reset the drive by repowering it to make it function properly after removing above problems.





## 12. Troubleshooting

In the event that your drive doesn't operate properly, the first step is to identify whether the problem is electrical or mechanical in nature. The next step is to isolate the system component that is causing the problem. As part of this process you may have to disconnect the individual components that make up your system and verify that they operate independently. It is important to document each step in the troubleshooting process. You may need this documentation to refer back to at a later date, and these details will greatly assist our Technical Support staff in determining the problem should you need assistance.

Many of the problems that affect motion control systems can be traced to electrical noise, controller software errors, or mistake in wiring.

#### **Problem Symptoms and Possible Causes**

Symptoms	Possible Problems
	No power
	Microstep resolution setting is wrong
Motor is not rotating	DIP switch current setting is wrong
	Fault condition exists
	The drive is disabled
Motor rotates in the wrong direction	Motor phases may be connected in reverse
The drive in fault	DIP switch current setting is wrong
The drive in fault	Something wrong with motor coil
	Control signal is too weak
	Control signal is interfered
Erratic motor motion	Wrong motor connection
	Something wrong with motor coil
	Current setting is too small, losing steps
	Current setting is too small
Motor stalls during acceleration	Motor is undersized for the application
Motor stans during acceleration	Acceleration is set too high
	Power supply voltage too low
	Inadequate heat sinking / cooling
Excessive motor and drive heating	Automatic current reduction function not being utilized
	Current is set too high



## 13. Warranty

#### **Twelve Month Warranty**

Leadshine Technology Co., Ltd. warrants its products against defects in materials and workmanship for a period of 12 months from shipment out of factory. During the warranty period, Leadshine will either, at its option, repair or replace products which proved to be defective.

#### **Exclusions**

The above warranty does not extend to any product damaged by reasons of improper or inadequate handlings by customer, improper or inadequate customer wirings, unauthorized modification or misuse, or operation beyond the electrical specifications of the product and/or operation beyond environmental specifications for the product.

Obtaining Warranty Service

To obtain warranty service, please contact your seller to obtain a returned material authorization number (RMA) before returning product for service.

#### **Shipping Failed Products**

If your product fail during the warranty period, please contact your seller for how and where to ship the failed product for warranty or repair services first, you can also e-mail customer service at tech@leadshine.com to obtain a returned material authorization number (RMA) before returning product for service. Please include a written description of the problem along with contact name and address.

